


Existing condition of the substructure (piers)

Ranges from poor to fair



Pictures of the bridge's pier caps show previous repairs and deteriorating concrete that can be pulled off by hand.



The pictures above show two different angles of a previous repair/patch failing on the same pier. The pictures below also show deteriorated concrete with exposed (rusting) steel reinforcement.

